

Pictures of Flooding in Acton via the Acton Town Council

Flooded intersection of Smith and Crown Valley just south and downstream of Park in Acton



Second view of intersection of Crown Valley and Smith looking north east in Acton



View of flood area from vehicle driving down Crown Valley at Escondido in Acton



Flooded intersection of Crown Valley and Escondido at the Acton Park



Intersection of Smith and Crown Valley during flash flood of August 2017



School bus on Crown Valley forced to drive near the middle of the road to avoid high flood areas



View from Escondido adjacent to Park looking at Crown Valley Road during flash flood of August 2017



View of flooded intersection of Smith and Crown Valley looking north toward the park located upstream



View of intersection of Crown Valley and Smith looking northeast



View toward Acton's Downtown Shopping Center along Crown Valley Road just south of park

